

Work Order ID 144253

144253

Page 1

April 08, 2016 2:31:06 PM

Item ID: D4785-115 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: Rib Assembly
 Start Date: 5/2/2016 Start Qty: 4.00
 Required Date: 5/13/2016 Req'd Qty: 4.00
 Reference: *SH 16* Cust Item ID:
 Customer:

Approvals: Process Plan: *SH* Date: **20160408** Tooling: Date: Run Start ***NR1***
 QC: Date: SPC (Y/N): Date: Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D4785	B

100 0.00 ***100*** *4* **MAY 05 2016** **DAS 24 9-89**
 Large Fab Memo 0.03
 Large Fab 1- Pick D4306-1 and drill and chamfer hole as per dwg D4785 using DT9921

105 QC6- Inspect dimensions to drawing 0.00 ***105*** *4* **MAY 05 2016** **DAS 43 9-89**
 QC Memo 0.00
 Quality Control

107 Weld per dwg A/R S.S. rod Batch: **132613** 0.00 ***107*** *4* **MAY 05 2016** **DAS 24 9-89**
 Large Fab Memo 0.00
 Large Fab 1- Use DT10159 for placing and tacking bushing, remove before welding.
 2- Weld bushing as per dwg D4785
 3- Grind welds flush

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____							
Misidentified ☐	Past Due ☐								

Work Order ID 144253

April 08, 2016 2:31:06 PM

144253

Page 2

Item ID: D4785-115

Accept

N900040100

Setup Start

NS1

Revision ID:

Stop

NS2

Item Name: Rib Assembly

Start Date: 5/2/2016 Start Qty: 4.00

4

Cust Item ID:

Required Date: 5/13/2016 Req'd Qty: 4.00

4

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start

NR1

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop

NR2

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
110	QC5- Inspect part completeness to step on W/O	0.00						DAS	
110							4x	43	MAY 09 2016
QC	Memo	0.00						9-89	
Quality Control									
120	QC10- Inspect visual per QSI004- ground welds	0.00						DAS	
120							4x	43	MAY 09 2016
QC	Memo	0.00						9-89	
Quality Control									
130	Identify as per dwg & Stock Location: <i>WVA 04</i>	0.00						DAS	
130							4x	43	MAY 09 2016
Packaging	Memo	0.00						9-89	
Packaging	LOCATION: WA004								

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
YAM									

Root Cause				FAULT CATEGORY			
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐		
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐		
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐		
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐		
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐		
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐		
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐		
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐		
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐		
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐		
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____					
Misidentified ☐	Past Due ☐						

Work Order ID 144253

April 08, 2016 2:31:06 PM

144253

Page 3

Item ID: D4785-115

Accept

N900040100

Setup

Start

NS1

Revision ID:

Stop

NS2

Item Name: Rib Assembly

Start Date: 5/2/2016 Start Qty: 4.00

4

Cust Item ID:

Required Date: 5/13/2016 Req'd Qty: 4.00

4

Customer:

Reference:

Approvals:

Process Plan: _____

Date: _____

Tooling: _____

Date: _____

Run

Start

NR1

QC: _____

Date: _____

SPC (Y/N): _____

Date: _____

Stop

NR2Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

140

QC21- Final Inspection - Work Order Release

0.00

140

QC

Memo

0.01

Quality Control

MAY 10 2016

MAY 09 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition			
				Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐					

Picklist Print

April 08, 2016 2:31:06 PM

Page 1

Work Order ID: 144253

144253

Parent Item: D4785-115

D4785-115

Parent Item Name: Rib Assembly

Start Date: 5/2/2016

Required Date: 5/13/2016

Start Qty: 4.00

Required Qty: 4.00

Comments: IPP REV:A 13.03.14 NEW ISSUE VERF:JLM
13.06.21 DWG REV.B DD VERF:JFS

IPP REV:B

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3759-1		Manufactured	No				Each	116.0000		8			DAS
D3759-1									**			MAY 05 2016	24
Bushing													9-89

Location

Loc Qty

Loc Code

WA004

116

141444

116

D4306-1

Manufactured No

Each

0.0000

4

MAY 05 2016

D4306-1

Rib

3144856

DAS
24
9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE


QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	

Root Cause				FAULT CATEGORY			
Environment ☐	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐
Design ☐	☐	Operator	☐	Bending	☐	Set-up	☐
Doc/Data ☐	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐
Equip/Tooling ☐	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐
Handling/Pre ☐	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐
Material ☐	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐
Internal Transport ☐	☐	Poor Information	☐	Crushing	☐	Countersink	☐
Tribal Knowledge ☐	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐
LOA ☐	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐
Substation ☐	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐
Past Expiry Date ☐	☐	Manufacturing Process	☐	OTHER :			
Misidentified ☐	☐	Past Due	☐				

ITEM NO.	QTY. -041	PART NUMBER	DESCRIPTION
1	X	D4785-041	LONG BASKET BASE ASSY, LH/RH
2	3	D4793-1	HANDLE PLATE
3	1	D4793-3	WIDE HANDLE PLATE
4	1	D4785-101	TUBULAR ASSEMBLY, LH/RH
5	2	D4672-1	BLANKING PLATE
6	2	D4021-5	BLANKING PLATE
7	1	D4020-1	MESH BASKET LONG, BASE
8	2	D4020-11	END MESH, BASKET
9	3	D4016-1	HINGE HALF, BASE
10	2	D2931	BUMPER
11	2	D2581	MOUNTING BRACKET
12	6	AN3-10A	BOLT
13	2	MS20600AD4W3	RIVET
14	6	MS21042L3	NUT
15	2	NAS1149DN832J	WASHER (AN960JD8)
16	12	NAS1149F0332P	WASHER (AN960-10L)



D4785-041 LONG BASKET BASE ASSY, LH/RH

NOTES:


- 1) MATERIAL: N/A
- 2) FINISH: POWDER COAT WHITE (4.3.5.2) PER DART QSI 005 4.3
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: NONE
- 7) WEIGHT: 50.42 lbs APPROX
- 8) INSTALL AFTER FINISH
- 9) MASK HOLES PRIOR TO POWDER COAT
- 10) WELD PER DART QSI 004

B	REPLACE D3916-5 WITH D4785-117 (ZIN B5-4, B4-4, B5-7); REVISE D4785-5 DIMENSION (ZIN B5-5)	RF	13.06.11
A	NEW ISSUE	RF	13.05.24
REV	DESCRIPTION	BY	DATE
DESIGN	RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	RF	DRAWING NO. D4785	REV. B
CHECKED	DC	SHEET 1 OF 7	
MFG. APPR.	DS	TITLE LONG BASKET BASE ASSY	SCALE NTS
APPROVED	CH	COPYRIGHT © 2013 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	
DATE	13.06.11		

120160408
SA 144253
RELEASED
2013-06-20
D

TRIM MESH LOCALLY
Ø0.50 - Ø0.60
TO CLEAR BUSHINGS
TYP

D4021-1
MESH



TACK WELD MESH
AT EVERY AVAILABLE
LOCATION

DETAIL C D7-2

0.75

A
B7-3

D4785-041 LONG BASKET BASE ASSY, LH/RH
(MESH SHOWN LOCALLY FOR CLARITY)

14 PL
(AROUND TAB, TYP
AND AT BTH ENDS)

0.76
TYP

D4672-1
BLANKING PLATE
2 PL

D4785-101
TUBULAR ASSY

D2931 BUMPER
NAS1149DN832J WASHER
MS20600AD4W3 RIVET
2 PL 8

D2581
MOUNTING BRACKET
2 PL


D4016-1
HINGE HALF, BASE
3 PL

D4793-3
HANDLE PLATE
LOCATED ON BASKET
BACK SIDE


D4793-1
HANDLE PLATE
3 PL

RELEASED
2013-06-20


DESIGN	RF	DART AEROSPACE LTD	
DRAWN	RF	HAWKESBURY, ONTARIO, CANADA	
CHECKED	PC	DRAWING NO.	REV. B
MFG. APPR.	PC	D4785	SHEET 2 OF 7
APPROVED	PC	TITLE	SCALE
DE APPR.	PC	LONG BASKET BASE ASSY	NTS
DATE	13.06.11	COPYRIGHT © 2013 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	




SECTION A-A 87-2




SECTION VIEW B-B A2-2



SECTION D-D D6-2



SECTION F-F C6-2
TYPICAL ON 3 PL




DETAIL E D2-3

RELEASED
2013-06-20

DESIGN	RF	DART AEROSPACE LTD	
DRAWN	RF	HAWKESBURY, ONTARIO, CANADA	
CHECKED	DL	DRAWING NO.	REV. B
MFG. APPR.	DL	D4785	SHEET 3 OF 7
APPROVED	DL	TITLE	SCALE
DE APPR.	DL	LONG BASKET BASE ASSY	NTS
DATE	13.06.11	COPYRIGHT © 2013 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	


ITEM NO.	QTY.	PART NUMBER	DESCRIPTION
1	X	D4785-101	TUBULAR ASSEMBLY
2	2	D4785-1	RIB
3	3	D4785-5	RIB
4	4	D4785-115	RIB ASSEMBLY
5	2	D4785-117	RIB ASSEMBLY
6	2	D4785-3	RIB
7	3	D4017-7	RIB
8	1	D4034-041	AFT UPPER RIB ASSY
9	1	D4034-043	FWD UPPER RIB ASSY
10	2	D3916-5	RIB, LIGHT
11	1	D3913-1	RIB
12	1	D3913-3	RIB
13	1	D3913-9	HINGE RIB



- NOTES:
- 1) MATERIAL: N/A
 - 2) FINISH: NONE
 - 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
 - 4) UNITS: INCHES UNLESS OTHERWISE NOTED
 - 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
 - 6) IDENTIFICATION: NONE
 - 7) WEIGHT: 28.65 lbs
 - 8) WELD PER DART QSI 004

D4785-101 TUBULAR ASSEMBLY, LH/RH

DESIGN	RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	RF		
CHECKED	SC	DRAWING NO.	REV. B
MFG. APPR.	SC	D4785	SHEET 4 OF 7
APPROVED	SC	TITLE	SCALE
DE APPR.	SC	LONG BASKET BASE ASSY	NTS
DATE	13.06.11	COPYRIGHT © 2013 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	




NOTES:

- 1) MATERIAL: AISI 304/316 SEAMLESS STAINLESS STEEL SQUARE TUBE, 0.50 x 0.50 x 0.049 WALL
PER ASTM A554 OR ASTM A269 MILL FINISH
REF DART SPEC. M304TS0.500W.049
- 2) FINISH: NONE
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: NONE
- 7) WEIGHT: SEE ASSEMBLED WEIGHTS

DESIGN	RF	DART AEROSPACE LTD	
DRAWN	RF	HAWKESBURY, ONTARIO, CANADA	
CHECKED	SC	DRAWING NO.	REV. B
MFG. APPR.	NS	D4785	SHEET 5 OF 7
APPROVED	#	TITLE	SCALE
DE APPR.	#	LONG BASKET BASE ASSY	NTS
DATE	13.06.11	COPYRIGHT © 2013 BY DART AEROSPACE LTD	
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR DISSEMINATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.			

RELEASED
2013-06-20
WJ

ITEM NO.	QTY. -115	PART NUMBER	DESCRIPTION
1	X	D4785-115	RIB ASSEMBLY
2	1	D4306-1	RIB
3	2	D3759-1	BUSHING



D4785-115 RIB ASSEMBLY
MAKE FROM D4306-1 RIB


RELEASED
2013-06-20
JMD

NOTES:

- 1) MATERIAL: D4306-1 RIB
- 2) FINISH: NONE
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: NONE
- 7) WEIGHT: 1.80 lbs
- 8) WELD PER DART QSI 004

DESIGN	RF	DART AEROSPACE LTD	
DRAWN	RF	HAWKESBURY, ONTARIO, CANADA	
CHECKED	JL	DRAWING NO.	REV. B
MFG. APPR.	JL	D4785	SHEET 8 OF 7
APPROVED	JL	TITLE	SCALE
DE APPR.	JL	LONG BASKET BASE ASSY	NTS
DATE	13.06.11	COPYRIGHT © 2013 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

ITEM NO.	QTY. -117	PART NUMBER	DESCRIPTION
1	X	D4785-117	RIB ASSEMBLY
2	1	D4306-1	RIB
3	2	D4021-9	BUSHING



D4785-117 RIB ASSEMBLY 
MAKE FROM D4306-1 RIB

NOTES:

- 1) MATERIAL: D4306-1 RIB
- 2) FINISH: NONE
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: NONE
- 7) WEIGHT: 1.81 lbs
- 8) WELD PER DART QSI 004

RELEASED
2013-06-20

DESIGN	RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	RF		
CHECKED		DRAWING NO.	REV. B
MFG. APPR.		D4785	SHEET 7 OF 7
APPROVED		TITLE	SCALE
DE APPR.		LONG BASKET BASE ASSY	NTS
DATE	13.06.11	COPYRIGHT © 2013 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR DISSEMINATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	